

General Environmental Incident Summary

Incident: 3443 **Date/Time Notice:** 8/31/2014 1900 **DEM Incident No:**
Responsible Party: ONEOK
Date Incident: 8/31/2014 **Time Incident:** 1715 **Duration:** 15 minutes
County: Williams **Twp:** 155 **Rng:** 98 **Sec:** 7 **Qtr:** SW SE
Lat: 48.25610 **Long:** -103.32690 **Method:** Navigation quality GPS
Location Description: Epping Compressor Station
1220758th Street WestEppingND58843
Submitted By: Kim Rudningen **Affiliation:** Env. Specialist-ONEOK
Address: 2700 Lincoln Ave SE
City: Sidney **State:** MT **Zip:** 59270

Received By:

Contact Person: Kim Rudningen
2700 Lincoln Ave SE
Sidney, MT 59270

Distance Nearest Occupied Building: 1 Miles **Release Contained:** Yes

Type of Incident: Tank Overflow

Description of Released Contaminant: Natural Gas Condensate

Volume Spilled: 50.00 gallons **Ag Related:** No

EPA Extremely Hazardous Substance: Unknown **Reported to NRC:** No

Cause of Incident:

While the operator was filling the condensate tank, the tank was overfilled by 50 gallons. The overflow ran down the tank and was contained within the secondary containment dike.

Risk Evaluation:

There are no immediate health hazards associated with this release.

of Fatalities: **# of Injuries:** **Affected Medium:** 03 - soil

Potential Environmental Impacts:

This spill was contained within the secondary containment system and will not have any other potential environmental impacts.

Action Taken or Planned:

The spill was contained within the secondary containment. There were no emergency actions that were required due to this release.

Wastes Disposal Location: The contaminated soil will be removed to a temporary storage container, and will then be disposed of at a permitted disposal facility.

Agencies Involved:

Updates

Date: 8/31/2014

Status: Reviewed; Followup Required

Author: Roberts, Kris

Updated Volume:

Notes:

Compressor Station release. Follow-up is necessary.

Date: 9/2/2014

Status: Reviewed; Followup Required

Author: Martin, Russell

Updated Volume:

Notes:

Release due to tank overflow at compressor station. Followup is necessary.

Date: 9/3/2014

Status: Inspected

Author: Washek, Sandi

Updated Volume: 50.00 gallons

Notes:

Arrived on site. Weather was sunny with wind out of the NE at 7-10 mph. The spill area had been scraped up into a pile. The area impacted was about 20x10 feet. No product came off the site; all was contained within the fence yard. The soil will be disposed at DHI. No further followup needed.